



Liquid paint touch-up instructions

- 1) Slightly sand the damaged area.
- 2) Clean the surface with a mild solvent.
- 3) Apply a primer.
- 4) Apply the liquid paint where needed with a paint brush or spray paint.

Powder coating touch-up instructions

- 1) Slightly sand the damaged area.
- 2) Clean the surface with a mild solvent.
- 3) Apply a primer.
- 4) Pour a small amount of powder into the empty container.
- 5) Add liquid catalyst and mix until you achieve the right color and texture.
- 6) Apply the mixture to the needed area using a paint brush.

Note: Do not mix all of the catalyst into the powder.

THE NEW SOURCE OF LIGHTING



Quattro Lighting 2154, de la Province, Longueuil, QC, Canada, J4G 1R7
Tel: 450-651-2250 Fax: 450-651-6129

